

RPS RETURN PROCEDURES



Lids and Trays, both the 10# and 20# components are to be stacked and banded on a pallet as shown in the two (2) above photo's. The number of units per pallet to be determined by the customer.



Remaining pallets are to be stacked upon each other and banded, as shown above. The number of pallets per stack to be determined by the customer.